

American Research Center in Egypt, Inc. - Egyptian Antiquities Project  
**PHOTOGRAPHIC RECORD SHEET: 35 mm B & W NEGATIVES**

Photographer (s): E.C. Brock

Film roll #: EG - BW 30302

Image Date (s) : November 12, 2002

Subject (s), with Building Location (s): Tomb of Anen, TT 120, West Bank, Luxor

Comments:

FRAME#      VIEW - e.g. exterior, interior, detail of..., view looking NW, South Facade, etc.

- 1 View of rubble wall built above tomb, view looking south. Photo: E.C. Brock
- 2 View of rubble wall built above tomb, view looking south. Photo: E.C. Brock
- 3 View of rubble wall built above tomb, view looking south. Photo: E.C. Brock
- 4 View of rubble wall built above tomb, view looking north west. Photo: E.C. Brock
- 5 View of rubble wall built above tomb, view looking north west. Photo: E.C. Brock
- 6 View of rubble wall built above tomb, view looking north east. Photo: E.C. Brock
- 7 Cabinet open on rekhyt painting. Photo: E.C. Brock
- 8 Cabinet doors closed on Inner Room. Photo: E.C. Brock
- 9 Cabinet doors open on Inner Room. Photo: E.C. Brock
- 10 Restored Pillar 4. Photo: E.C. Brock
- 11 Metal supports for unstable rock in Inner Room. Photo: E.C. Brock
- 12 Close-up of base of metal supports. Photo: E.C. Brock
- 13
- 14
- 15
- 16
- 17
- 18
- 19

Return all completed Photographic Record Sheets to:  
ARCE/EAP, 2 Midan Qasr al Dubara, Garden City, Cairo, Egypt

**PHOTOGRAPHIC RECORD SHEET: 35 mm B & W NEGATIVES**

- 
- 20 View of south end of Hall showing restored wall with mud-brick construction. Photo: E.C. Brock
- 
- 21 View of interior of east wall, south end, showing restored wall. Photo: E.C. Brock
- 
- 22 View of metal grid and niche for false door above, looking south. Photo: E.C. Brock
- 
- 23 View looking west of niche constructed above protection to hold Amenhotep III relief. Photo: E.C. Brock
- 
- 24 View looking east of new lintel above entrance to Hall. Photo: E.C. Brock
- 
- 25 View looking east of north end of Hall showing restored upper level and flashing. Photo: E.C. Brock
- 
- 26 View looking north of north end of Hall showing restored upper level and flashing. Photo: E.C. Brock
- 
- 27 View looking east of new lintel above entrance to Hall. Photo: E.C. Brock
- 
- 28
- 
- 29
- 
- 30
- 
- 31 View looking west of cabinet with doors open on Amenhotep III and Tiy painting. Photo: E.C. Brock
- 
- 32 Whole view of cabinet, south end. Photo: E.C. Brock
- 
- 33 Whole view of cabinet, north end. Photo: E.C. Brock
- 
- 34 View looking west of cabinet with doors open on Amenhotep III and Tiy painting. Photo: E.C. Brock
- 
- 35
- 
- 36
- 
- 37
- 
- 38
- 
- 39
- 
- 40
-