

American Research Center in Egypt, Inc. - Egyptian Antiquities Project
PHOTOGRAPHIC RECORD SHEET: 35 mm SLIDES

Photographer (s): L.P. Brock, E.C. Brock, F. Dzikowski Film roll #: EG S 253 02

Image Date (s) : October 2 – November 28, 2002

Subject (s), with Building Location (s): Tomb of Anen (TT 120) West Bank, Luxor

Comments:

FRAME#	VIEW - e.g. exterior, interior, detail of....., view looking NW, South Facade, etc.
1	Close-up of Ewa Paradowska retouching green frit area in lower part of *. Photo: E.C. Brock
2	Doors open on <i>rekhyt</i> scene enclosed in new protective covering. View looking west. Photo: E.C. Brock
3	South east corner of Hall, view looking south, of grid over burial chamber, shown open. Photo: E.C. Brock
4	View looking north, interior of Hall, north end, showing flashing and mud-brick restoration of the upper part. Photo: E.C. Brock
5	Protective cabinet in mid-stages of construction. View looking west. Photo: L. Pinch-Brock.
6	Full view of doors of new cabinet open on Amenhotep III and Tiy scene. Photo: E.C. Brock
7	View looking east of top of east wall of Hall, showing detail of mud-brick restoration. Photo: E.C. Brock.
8	Workmen completing construction of one of three rubble walls above tomb. View looking south. Photo: E.C. Brock
9	Whole view looking east of completed protective cabinet with all doors closed. Photo: E.C. Brock
10	View taken from top of wall of doors of new cabinet open on Amenhotep III and Tiy scene. Photo: E.C. Brock
11	View of south-east end of Hall showing discovery of opening into burial chamber. Photo: E.C. Brock
12	View of rubble wall constructed on top of tomb. View looking north. Photo: E.C. Brock
13	“Niche” constructed above tomb to hold completed Amenhotep III relief. Photo: E.C. Brock
14	View of south-east corner of Hall, looking south, showing niche for false door above burial chamber. Photo: E.C. Brock
15	View looking west of top of east wall, restored with mud brick. Photo: E.C. Brock
16	View looking east from top of tomb showing general geography of area. Photo: E.C. Brock
17	Doors of protective cabinet open on metal supports. View looking east. Photo: E.C. Brock
18	Grid over burial chamber, door closed. Full view looking south. Photo: E.C. Brock
19	View of interior of Hall, looking east, showing new mud-brick lintel over doorway. Photo: E.C. Brock
20	View of small rubble wall built above tomb to prevent entry of rainwater. Photo: E.C. Brock

Return all completed Photographic Record Sheets to:
ARCE/EAP, 2 Midan Qasr al Dubara, Garden City, Cairo, Egypt
Tel. (202) 794 8622, (202) 794 4681 Fax: (202) 794 8622. E-mail: arceeap@internetegypt.com

American Research Center in Egypt, Inc. - Egyptian Antiquities Project
PHOTOGRAPHIC RECORD SHEET: 35 mm SLIDES

Photographer (s): L.P. Brock, E.C. Brock, F. Dzikowski Film roll #: EG S 254 02

Image Date (s) : October 2 – November 28, 2002

Subject (s), with Building Location (s): Tomb of Anen (TT 120) West Bank, Luxor

Comments:

FRAME#	VIEW - e.g. exterior, interior, detail of....., view looking NW, South Facade, etc.
--------	---

1	Full view of completed rubble wall, looking north. Photo: E.C. Brock
---	--

2	Full view of south reveal, entrance to Inner Room, after conservation, looking south. Photo: F. Dzikowski.
---	---

3	Close-up of small female figure, east end, north wall, Inner Room. Photo: F. Dzikowski.
---	--

4	
---	--

5	
---	--

6	
---	--

7	
---	--

8	
---	--

9	
---	--

10	
----	--

11	
----	--

12	
----	--

13	
----	--

14	
----	--

15	
----	--

16	
----	--

17	
----	--

18	
----	--

19	
----	--

20	
----	--

Return all completed Photographic Record Sheets to:
ARCE/EAP, 2 Midan Qasr al Dubara, Garden City, Cairo, Egypt
Tel. (202) 794 8622, (202) 794 4681 Fax: (202) 794 8622. E-mail: arceeap@internetegypt.com