







B72



Cracks



Smears of Previous Restoration



Vulnerable Edges (Losses of Original)



Loosely Bound Paint (Powdering)



Flaking



Wasps Nests



Retouching Over Fills



Retouching Over Original



Salts



Water Damage



Grouting (Detached Plaster)