

	B72
	Cracks
	Smears of Previous Restoration
	Vulnerable Edges (Losses of Original)
	Loosely Bound Paint (Powdering)
	Flaking
	Wasps Nests
	Retouching Over Fills
	Retouching Over Original
29	Salts
	Water Damage
	Grouting (Detached Plaster)